

LEGEND	
	CURRENT TRANSFORMER
	FAULT SIGNAL
	SIGNAL LIGHT
	SURGE PROTECTION DEVICE
	PHASE CONTROL
	PUSH BUTTON
	1 PHASE FUSE
	3 PHASE FUSE
	3 POSITION SELECTOR SWITCH
	CONTACTOR
	1 PHASE MINATURE CIRCUIT BREAKER
	3 PHASE MINATURE CIRCUIT BREAKER
	1 PHASE MOTOR PROTECTION CIRCUIT BREAKER
	3 PHASE MOLDED CASE CIRCUIT BREAKER
	3 PHASE RESIDUAL CURRENT CIRCUIT BREAKER
	1 PHASE RESIDUAL CURRENT CIRCUIT BREAKER
	BYPASS RELAY
	3 PHASE CHARGER FUSE
	1 PHASE CHARGER FUSE
	MULTIMETER

- پیمانکار موظف است که بیش از آغاز هر قسمت از کار تمام نقشه های مربوط به آن قسمت را با دقت کنترل نماید و در صورت مشاهده ایهام ، نواقص و یا عدم تطابق قبل از اجرا موارد را به مهندس مشاور منعکس نماید .

Drawing Info

.....	DA	REVISION	تغییرات
.....	IFC	STATUS	وضعیت
.....	MS/1-18	DATE	تاریخ
.....	DESIGNED BY PH2	طراح
.....	CHECKED BY PH2	کنترل
.....	DESIGNED BY PH1	طراح
.....	APPROVED BY PH1	تصویب
.....	COORDINATED BY PH1	هماهنگی کننده
.....	PROJECT MANAGER	مدیر پروژه

SIZE	سایز	Group	DOCUMENT	SEQUENCE	REVISION
A3		گروه	نوع مدرک	شماره مدرک	ویرایش
SHEET		Mech	DWG		00
		SCALE	PROJECT C.		PHASE
UNITS	واحد	مقیاس	کد پروژه		فاز
m			SIRJ		P2

