

LEGEND	
	CURRENT TRANSFORMER
	FAULT SIGNAL
	SIGNAL LIGHT
	SURGE PROTECTION DEVICE
	PHASE CONTROL
	PUSH BUTTON
	1 PHASE FUSE
	3 PHASE FUSE
	POSITION SELECTOR SWITCH
	CIRCUIT BREAKER
	1 PHASE MINATURE CIRCUIT BREAKER
	3 PHASE MINATURE CIRCUIT BREAKER
	1 PHASE MOTOR PROTECTION CIRCUIT BREAKER
	3 PHASE MOLDED CASE CIRCUIT BREAKER
	1 PHASE RESIDUAL CURRENT CIRCUIT BREAKER
	3 PHASE RESIDUAL CURRENT CIRCUIT BREAKER
	BIPHASIC RELAY
	1 PHASE CARRIER FUSE
	3 PHASE CARRIER FUSE
	WATTMETER

- پیمانکار موظف است که بیش از آغاز هر قسمت از کار تمام نقشه های مربوط به آن قسمت را با دقت کنترل نماید و در صورت مشاهده ایهام ، نواقص و یا عدم تطابق قبل از اجرا موارد را به مهندس مشاور منعکس نماید .

Drawing Info

-----	-----	0A	REVISION	تغییرات
-----	-----	IFC	STATUS	وضعیت
-----	-----	MD-5-18	DATE	تاریخ
-----	-----	درجہ	DESIGNED BY PH2	طراح
-----	-----	---	CHECKED BY PH2	کنترل
-----	-----	پیشہ منظم س. س. نیگی	DESIGNED BY PH1	طراح
-----	-----	---	APPROVED BY PH1	تصویب
-----	-----	احسان	COORDINATED BY PH1	هماہنگ کنندہ
-----	-----	احسان	PROJECT MANAGER	مشیر پروژه

SIZE A3	سایز	Group گروه	DOCUMENT نوع مدرک	SEQUENCE شماره مدرک	REVISION ویرایش
SHEET 02		Mech	DWG	MSW/01	00
UNITS m	واحد	SCALE مقیاس	PROJECT C. کد پروژه		PHASE فاز
			SIRJ		P2

